

Water District No. 34

**P. O. Box 53
Mackay, ID 83251
(208) 588-3137**

RECEIVED

APR 13 2001

Department of Water Resources
Eastern Region

April 10, 2001

To all Antelope Irrigators:

A meeting was held on Monday, April 9, 2001 to discuss the north and south channels of Antelope Creek and their use during the 2001 irrigation season. All irrigators or their representatives were present at the meeting.

Those in attendance at the meeting were in agreement that two-thirds of the water in Antelope Creek would be delivered through the south channel with one-third being delivered through the north channel. It was also decided that the Watermaster would monitor the water level and determine when it is no longer beneficial to divide the stream flow at which point all water will be delivered through the south channel. The Watermaster will instruct Mike Seal to make these changes.

In the future, questions regarding the use of the north and south channels of Antelope Creek should be directed to the Watermaster. He may be reached in his office at 588-3137 or at home at 588-2551.

DR:stn

Cc: Greg Taylor
Eastern Region IDWR